



CNC Machinist

Overview

The CNC Machinist is responsible for safely machining good quality parts, adhering to all job traveler requirements, and meeting delivery deadlines.

Responsibilities

- Responsible for the safe operation of the CNC machine
- Able to perform machine set-ups
- Ensure that proper tooling and programs are used
- Make adjustments to the machine and tooling as required
- Report machine malfunctions, abnormalities and problems to the supervisor
- Ensure that all fluid levels are maintained
- Maintain traceability on all parts
- Read and follow job traveler instructions
- Read and interpret blueprints
- Keep work area clean
- Communicate with incoming and outgoing shift personnel on job status
- Other duties as assigned

Requirements

- High School Diploma or GED
- Able to pass the pre-employment drug screen
- Capable of lifting twenty-five (25) pounds and working, standing and walking for extended periods
- Proficient in operating Mori Seiki and Mazak controls.
- Previous experience with premium threading, emphasis on TenarisHydril connections.